


Cylinders 1 2 and 3 are shown 4 5 and 6 will be a copy of this



You need to double up on module and coil

Late model Bmw's with a Siemens crank pickup use a hall 60-2 ecu

BMW 6 Cyl Coil On Plug